944-SPEC - 944SPEC - low cost wheel to wheel racing Generated: 17 October, 2025, 09:45

14.

Develope at the Deint CASII race Oct 0.10
Porsches at the Point CASH race Oct 9-10 Posted by pixrken - 21 Sep 2010 00:27
Hi Guys,
The 2010 Porsches at the Point, 944-Spec AutoPoint Challenge will be held at Infineon raceway October 9th-10th.
This is NorCal 944-Spec's big race and all regions are welcome!
I believe we'll have close to \$3,000 in combined CASH, contingencies and prizes.
Let's start the roll call:
1. Ken #89
2. Greg #43
3. Steve L. #72
4. Cameron #42
5. Ron #130
6. Ivan #38
7. Dan #4
8. Jerry #552
9. Sid #400
10. Rick #30
11.
12.
13.

944-SPEC - 944SPEC - low cost wheel to wheel racing Generated: 17 October, 2025, 09:45

Re:Porsches at the Point CASH race Oct 9-10 Posted by 944Racer72 - 21 Sep 2010 00:34
l'm in
Re:Porsches at the Point CASH race Oct 9-10 Posted by Salanis42 - 21 Sep 2010 03:30
I'm about 60% certain I'll be there now that I'm back to being employed. Still need to slide some funds around.
Where the heck is the registration for the event? There isn't a link on the nasanorcal site.
Re:Porsches at the Point CASH race Oct 9-10 Posted by pixrken - 21 Sep 2010 14:51
Hi Cameron,
Hope to see you there.
Here's the sign up URL
https://www.nasaproracing.com/event/1119
Re:Porsches at the Point CASH race Oct 9-10 Posted by JerryW - 21 Sep 2010 23:36
I'm hoping to make it - looks like we were right and it's the clutch.
Re:Porsches at the Point CASH race Oct 9-10 Posted by 944Racer72 - 21 Sep 2010 23:56

944-SPEC - 944SPEC - low cost wheel to wheel racing

Generated: 17 October, 2025, 09:45

Jerry,

Did the friction material break off from the center hub? I assume this is a spring-centered clutch? I've seen several fail at the sheet metal tabs that go from the spring center to the friction ring.

The most direct way to correct this failure mode is to use the turbo clutch disk and keep everything else. It is much stronger and fits all the stock stuff. The clutch disk is free per the rules but you have to keep the stock pressure plate etc.
